

MONUMENT RECORD

Corner I.D. #



E-11

STATE OF INDIANA - COUNTY OF MONROE


Section Eighteen (18) , Township 9 North , Range 1 East

Monument Description & Remarks: Found 5/8" Rebar w/yellow plastic cap at
East 1/4 corner of section. Rebar was flush w/ground and firmly in place.
Plastic cap reads "Ind Gas Bauer • R.L.S. #S0457".

Recovery Tie Drawing



● At Corner



Not To Scale

State of Indiana

County of Monroe

I, Michael W. Friley, County Surveyor, hereby certify
that this document was prepared under my direction in
accordance with the provisions of Section 17-3-64-4
through 17-3-64-8 of the Indiana Code, being Acts of 1965,
Chapter 319; and the above data is given under my hand and
seal this 29th day of January, 19 96 A.D.

Space
Reserved For
Recording
Officer

Indiana Registered Land Surveyor No. _____ or

Monroe County Surveyor's Office
United States Government Agency

Monroe County Surveyor
Title

Field Book:

96-01

Page:

7

ALAN McCLELLAN
D.M. FRILEY

SEC 7, T9N, R1E
1-17-96 52°F
PT. SUNNY

2" x 7"

FIND SANDSTONE STONE
AT E. 1/4 COR.
checked rec list 11.86'
N. & S. For Ind. Treaty
N. EVIDENCE FND N. & S.
BUT FNC. FROM STONE
going South East, S.W. 1/4
IND Treaty should be
Approx N 50° 52' W. From
previous survey stone
checks in better
SECTION AS 1/4 COR.
I SUSPECT STONE MISTAKEN
AS TREATY MONUMENT
WHICH EXPLAINS N 41° W
FNC.

SEE TIES

NEXT PAGE (3)

1-17-96
P.K. @ BASE
E. SIDE 8"
S. ASSAFASS

E. 1/4 COR
SEC 7, 9N, 1E (2)

STONE IS SUNK
IN GRND. 0.3' x
0.8' x 0.7'
OUT OF GRND.

